



Folding Table 470


Hardware List:	Bolt M6x40 / washer / nut	15
	Bolt M6x70 / washer / nut	2
	Lock	2
	Rubber Plug	4
	Wood Block	1




Step 1, Draw 2 lines for the 2 side legs. Put the side leg with short hinge align the line and drill 5 holes. Fasten 5 bolts with washers and nuts. When drill holes for the bolts, make sure to put a wood board underneath, otherwise the table top will split



Step 2, make the side leg vertical in 90 - 91 degree and then position the lock. Drill hole for the lock and 2 bolts M6*40. Fasten the bolts with washers and nuts



Step 3, put the side leg with high hinge align the drawing line, drill 5 holes for the bolts and fasten 5 bolts with washers and nuts.



Step 4, make the side leg vertical in 90 - 91 degree and then position the lock and wood block. Drill holes for the lock and wood block. Use 2 bolts M6*70. Fasten the bolts with washers and nuts. Mount 4 rubber plugs.